

Site Amenities-BY SUPERIOR RECREATIONAL PRODUCTS Model # B4GW-RC SUPERIOR* RECREATIONAL PRODUCTS A PLAYCORE" Company


2/18/2022 Page 1 of 8





2/18/2022 Page 2 of 8

TOOLS REQUIRED













PRODUCT SPECIFICATIONS

B4GW-RC GATEWAY BENCH WITHOUT BACK

Seats: 2x4 planks are made from a minimum of 96% post-consumer or post-industrial recycled plastic. Contains UV stabilizers to prevent fading. Seat support frame is made of 10 ga steel plate, 1" sch 40 pipe, and 5/8" solid rod. Electrically MIG welded.

Frame: Legs are cast aluminum.


Frame Coating: Steel is sandblasted to near white condition. Coated with zinc rich epoxy primer and top coated with electrostatic powder coat, oven cured.

Hardware: All fasteners are stainless steel.

Dimensions: 4' portable/surface mount bench without back. Seats are 26-1/2" wide x 48-3/8" long. Seat height is 18-1/2" from the ground to the top of the seat. The overall dimensions are 52" x 27-1/4" x 25-5/8".



COMPONENTS




ITEM NO.	PartNo	DESCRIPTION	QTY
1	11-01-CAST8	Durham Casted Aluminum Bench Frame	2
2	01-01-0633	49" Support Bar	1
3	01-01-0628	4' Recycled Flat Contour Frame - Welded	1
4	33-06-0093	3/8"-16 x 2-1/2" Button Head Bolt (SS)	6
5	33-02-0008	3/8" Flat Washer (SS)	4
6	33-02-0007	5/16" SS Washer	14
7	33-03-0013	3/8" Kep Nut (SS)	4
8	33-05-0034	5/16" x 1-1/4" lag bolt, SS	14
9	R48-2x4B-LB	2 x 4 Recycled Bench Bullnose Plank-lag bolts (4')	2
10	R48-2x4-LB	2 x 4 Recycled Bench Plank-lagbolt (4')	5

Optional Surface Mount Hardware: 3/8" x 3-1/2" Concrete Expansion Anchor Bolts (Not Included)



2/18/2022 Page 5 of 8

STEP 1




Attach the Recycled Seat Support to the Cast End Frames using the specified hardware.



2/18/2022 Page 6 of 8

STEP 2




Attach the 4' Recycled Bench Planks to the Seat Support, placing the 2 Bullnose Planks on the outside, as shown using the specified hardware.

Warning: Over tightening of the Lag Bolts may result in cracking and/or stripping out of the Planks.



2/18/2022 Page 7 of 8



2/18/2022 Page 8 of 8